## INDEX TO PHOTOGRAPHS

Twin Oaks Dairy Northwest of Metcalfe Road, off State Route 101 (Monterey Road) Coyote Vicinity Santa Clara County California

HABS CAL, 43-COYO.V, 2-

Documentation: 1 photocopy of 1977 site plan 22 exterior photos

8 data pages

CA-2016-1 Photocopy of site plan, Dene Hendrick, delineator, 1977, for the City of San Jose in cooperative agreement with the California Department of Transportation (from the San Jose Historical Museum).

Pete Asano, Photographer, August 9, 1978

CA-2016-2 CENERAL VIEW OF RESIDENCE (STRUCTURE 7) AND HORSE AND LIVERY STABLE (STRUCTURE 8) FROM NORTH

CA-2016-3 GENERAL VIEW OF FEED BARN (STRUCTURE 1), MILKING BARN (CENTER) (STRUCTURE 2) AND CORNER OF MILK HOUSE (STRUCTURE 3) FROM SOUTHEAST

CA-2016-4 GENERAL VIEW OF MILK HOUSE (STRUCTURE 3) AND STORACE SHED (STRUCTURE 4) FROM NORTHEAST

CA-2016-5 FEED BARN (STRUCTURE 1) SOUTHEAST END WITH WALL OF MILKING BARN (STRUCTURE 2) IN FOREGROUND

CA-2016-6 FEED BARN (STRUCTURE 1) FROM SOUTH

CA-2016-7 FEED BARN (STRUCTURE 1) INTERIOR VIEW OF MOW AREA

CA-2016-8 FEED BARN (STRUCTURE 1) INTERIOR VIEW OF NORTHEAST WORK AISLE

CA-2016-9 FEED BARN (STRUCTURE 1) INTERIOR VIEW OF SOUTHWEST MILKING AISLE WITH STANCHIONS

CA-2016-10 FEED BARN (STRUCTURE 1) DETAIL OF MILKING STANCHION AND HASP (CLOSED)

- CA-2016-11 FEED BARN (STRUCTURE 1) DETAIL OF MILKING STANCHION AND HASP (OPEN)
- CA-2016-12 MILKING BARN (STRUCTURE 2) VIEW FROM SOUTHEAST END
- CA-2016-13 MILKING BARN (STRUCTURE 2) DETAIL OF HAY TRAM
- CA-2016-14 MILK HOUSE (STRUCTURE 3) WEST (FRONT) AND NORTH (SIDE) ELEVATIONS
- CA-2016-15 MILK HOUSE (STRUCTURE 3) EAST (REAR) AND SOUTH (SIDE) ELEVATIONS
- CA-2016-16 MILK HOUSE (STRUCTURE 3) INTERIOR COOLER BOX
- CA-2016-17 STORAGE SHED (STRUCTURE 4) FROM NORTHEAST
- CA-2016-18 STRUCTURE 5 (COLLAPSED) FROM SOUTHWEST
- CA-2016-19 WAGON BARN (STRUCTURE 8) NORTHEAST (FRONT ELEVATION)
  FROM SOUTHEAST
- CA-2016-20 HORSE AND LIVERY STABLE (STRUCTURE 9) SOUTHEAST END
- CA-2016-21 HORSE AND LIVERY STABLE (STRUCTURE 9) FROM NORTHEAST
- CA-2016-22 HORSE AND LIVERY STABLE (STRUCTURE 9) VIEW OF INTERIOR
- CA-2016-23 HORSE AND LIVERY STABLE (STRUCTURE 9) INTERIOR VIEW OF STALLS